

---

Subject: Re: Any suggestions remarks on this design?

Posted by [Wayne Parham](#) on Mon, 03 Apr 2006 15:42:13 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I think 400Hz is probably an octave too high because folding generally attenuates higher frequencies. Standing waves develop inside that tend to make lower midrange output ragged. So crossover lower than 400Hz but otherwise it's probably a pretty good layout. Have you modeled it in Hornresp?

---