

---

Subject: Re: Consequences of non-optimal throat transition in mid and high frequency horns

Posted by [Cuppa Joe](#) on Tue, 20 Mar 2007 00:46:54 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I know that the BMS 2" coaxials have a little frequency spike just above the crossover point of 6.3kHz with their passive network. You might try an active crossover, if you're not using one already.

---