
Subject: Re: A Lowther question, please?
Posted by [kyle](#) on Thu, 01 Jul 2004 17:41:23 GMT
[View Forum Message](#) <> [Reply to Message](#)

It's a combination of a very powerful magnet and that the voice coil and gap are exposed to the elements. If you look between the phase plug and the whizzer you can see the small size of the gap. Even a tiny piece of debris will get jammed causing unpleasant sounds. That said, I used a PM6A with no covers since the early nineties with no problems.
