

---

Subject: Re: Newest acquisition 2 - 8" full range from Roland

Posted by [Don](#) on Wed, 15 Sep 2004 02:20:21 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

My point is the throat isn't the pointed tip since the driver is in the middle of the pipe. It doesn't act the same as if the driver were at the tip. Moving away from the tip makes a low pass function, does it not? Don

---