Subject: Re: Newest acquisition 2 - 8" full range from Roland Posted by GM on Wed, 15 Sep 2004 22:42:51 GMT

View Forum Message <> Reply to Message

>Moving the driver down will help null a ripple at some point in the FR curve, but the pipe still acts like a pipe. If you study Martin Kings page and Bobs page you can see that the upper closed area acts like a throat.====Only at Fp. Slide the driver down the horn and hear your gain above it disappear. GM