Subject: Re: Legend 875

Posted by akhilesh on Thu, 07 Oct 2004 17:11:00 GMT

View Forum Message <> Reply to Message

Thanks Wayne. Based on info I got, it seems to have an fs of 88 HZ, and a pretty steep fall off below 70HZ. I would say it needs a woofer, but os probably a good widebander. Needs a super tweeter as well. Thank for the pointer!-akhilesh