

---

Subject: Re: correction filter for Fostex fe206e in a Jeriko

Posted by [akhilesh](#) on Thu, 06 Jan 2005 15:35:00 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

HI Kane, You are right about the 206 curves. I'd run it clean first to see how the horn works, and then try a notch filter (+3db below 2000 Hz). IF that does not work, then try a notch filter at 200hz with a 3 db boost below that. let us know how it works out!-akhilesh

---