

---

Subject: Re: Floor bounce

Posted by [Wayne Parham](#) on Sat, 19 May 2007 03:56:12 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

When a driver is placed at ear height, the frequency where the floor bounce notch occurs is well above the port frequency. So port position isn't as relevant as driver position. Ceiling bounce is actually about right for the range of frequencies coming from the port though.

---