

---

Subject: Re: More line array questions using the Bandor 50mm driver?

Posted by [7V](#) on Sun, 05 Sep 2004 17:38:53 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Just one extra point, Norris. I would be inclined to keep the volume to below the 2.5 liters per drive unit that you quoted before. To minimize cone excursion and help power handling, keep the size to below 2 liters per driver. I believe that Qts will still be below 0.7 even as low as 1.5 liters.

---