
Subject: Re: CTC spacing probably isn't the reason
Posted by [Rick Craig](#) on Sat, 09 Sep 2006 02:55:28 GMT
[View Forum Message](#) <> [Reply to Message](#)

I also think that the cone profile is part of the issue. This is one of the reasons why I advise against using the small dome tweeters that won't cross very low.
