

---

Subject: Re: Needle Array

Posted by [Danse](#) on Mon, 06 Nov 2006 19:38:12 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Thanks Jim! Any thoughts on: half of 4/3/2/half of 2/T/half of 2/2/3/half of 4. A little concerned at the  $Z = 3.3\text{ohms}$ , just wondering with a passive crossover the inductors should bring the Z up a bit, but would be stable enough for the amp.

---