

---

Subject: negative going signal

Posted by [lcholke](#) on Wed, 07 Nov 2007 14:52:15 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi Lito, Is the tube mounted behind the driver and stuffed with dampening material? Is the tube partly closed on the back end? If the tube that reduces the negative signal is acting as a rear enclosure, then the cone travel may be being limited, reducing the Doppler distortion. Is the bass reduced also. Thanks-Linc

---