
Subject: Re: so I built these lines with a single tweeter
Posted by [Anonymous](#) on Sun, 27 Jan 2008 02:16:10 GMT
[View Forum Message](#) <> [Reply to Message](#)

NSB installation was a PITA. The frame lip problem. I used a precision rabbet after cutting the hole out, to recess the frame lip inside it. Then I used generic rope caulk found at partsexpress to gasket the driver.
