

---

Subject: Re: Hot wire knife?

Posted by [Cyclotronguy](#) on Wed, 01 Mar 2006 18:32:41 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

You would most likely want to have one wire in a serpentine pattern. The problem with parallel wires is that several always current hog, running way too hot... and others run too cool. One continuous loop and you get much more even temperature.Cyclotronguy

---