
Subject: Re: Measuring box tuning ?

Posted by [Wayne Parham](#) on Wed, 31 Dec 2003 22:07:30 GMT

[View Forum Message](#) <> [Reply to Message](#)

Hi Bill! You'll measure the impedance curve of the system and find f_l and f_h . After that, find f_b using the formulas shown in the post called "Measure impedance." Wayne
