

---

Subject: Re: For the record :)

Posted by [Bob Brines](#) on Thu, 22 Dec 2005 20:18:23 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Agreed! One you get all of the graphs and charts laid out, the black arts take over. Some stuff you see you can fix, some you can't. Then you hear stuff that you can't see. The same goes for modeling. If you don't start with a good set of assumptions, you will never achieve a good design. I see it all of the time. Guys will come up with a reasonable FR plot and announce to the world how good it will be, but when you look at the design parameters, you know it will never work. Modeling and measuring are just tools, and I need all of the help I can get, but in the end I have to sit down and listen. Bob

---