

---

Subject: Re: AK model 310 capacitor question

Posted by [Wayne Parham](#) on Wed, 07 Jun 2006 19:34:47 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I'm sure you've guessed it right. Check to see if they're power supply caps, which they most certainly must be. In that case, they are just ripple filters and a large value across the line (to ground) makes sense.

---