

---

Subject: Re: Help with Grunow Model: 660 Chassis:6C  
Posted by [Wayne Parham](#) on Thu, 21 Sep 2006 14:05:19 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Have you checked to make sure the potentiometer is connected properly? If wires to pins 1 and 3 are reversed, the volume knob works backwards like that.

---