

---

Subject: Re: Lenco 35

Posted by [Manualblock](#) on Mon, 20 Dec 2004 13:06:29 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

The unit is probably reverse wired. Has someone worked on it in the past?

---