
Subject: Re: Western Electric 555 Drivers
Posted by [Jim K](#) on Sun, 29 May 2005 04:23:01 GMT
[View Forum Message](#) <> [Reply to Message](#)

yeah.....big bucks for what?ya need the PS for it first of all.....(7 VDC at 6 amps!)...and then ya hope nobody pumped more than 5 watts thru the VC..I've got the sad results sitting on my bench.....and nobody to fix the VC....
