

---

Subject: 2nd Channel on a EICO ST-40

Posted by [DW Barnhard](#) on Mon, 19 Mar 2007 03:43:37 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I am having problems with my recently acquired EICO ST 40the 2nd channel is dead when I have the unit switched to stereo.When I select reverse the speaker in the 2nd channel works.When I select Mono both speakers work. I have a center speaker connected which works and is connected as indicated in the instructions.Any suggestions. DWB

---