
Subject: Re: OOOPS it just went bang!
Posted by [hitsware](#) on Fri, 07 Jan 2005 16:08:56 GMT
[View Forum Message](#) <> [Reply to Message](#)

Might be humming because it is driving a short. (the cap and or something else) It is good practice to put a lightbulb in series with the mains to limit current draw while working on SS circuits. This can save you from doing more damage and burning new parts if more than one failed component exists.....
