
Subject: Re: Peavey noise problem
Posted by [Paul C.](#) on Sun, 22 Jan 2006 02:29:14 GMT
[View Forum Message](#) <> [Reply to Message](#)

He says the chassis has only four 6L6 tubes. The rectifier is solid state.
