

---

Subject: Re: Pignose B-100 V picks up radio! AHHH  
Posted by [Damir](#) on Thu, 02 Mar 2006 19:11:02 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

First try to change guitar cabel, if problem persists see the input jack, and re-tighten it. Then - use shielded cabel from input jack to the electronics (shield grounding on the input end). Even adding a small cap (few tens of pF) on the input isn`t eliminated in extreme cases.

---