
Subject: Re: Marshall fade out fuzz
Posted by [Damir](#) on Thu, 02 Mar 2006 19:14:29 GMT
[View Forum Message](#) <> [Reply to Message](#)

Huh, it can be many things - from cold solder joint to the faulty component like PS cap.
Troubleshooting can be made with some (sinusoidal) input signal, and tracing the fault through the
amp, from output to the input. Tech?
