

---

Subject: Re: My impressions

Posted by [freddy](#) on Tue, 18 Oct 2005 17:30:11 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

missed all that - every little bit of heat reduction should help. - accidentally smoked an Eminence 15 w. 3" coil (9.1mm xmax overhang) with clipped sine and a tiny Servo 260 Samson in a couple of minutes at 20Hz with a tranform EQ box - didn't lock nor open but aroma pouring out of pole-piece then into vent to room smelt pretty nasty - lol

---