

---

Subject: Re:Smoky the Bear, says".....

Posted by [lon](#) on Tue, 26 Apr 2005 04:28:56 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

It's probably true, not legend. I had to look in the waste to see where the ember was that I had to poke out. Where there was that much smoke, there had to be some fire. The rototool spins at around 17,000 rpm. First few passes went ok. I'll have to upgrade the bit and take a smaller pass. Hell, it's a hobby-- no rush. But setup on this job for a bunch of zig zags is a drag. I'm leaving it go for a few days.

---