

---

Subject: Re: Solid State vs Vacuum Tube Finish  
Posted by [Bill Martinelli](#) on Sun, 11 Sep 2005 01:51:40 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

You should give Varnish a try some time. You can use tung oil and let it cure for a few days, then use 3 coats of varnish. make sure to sand between coats because varnish will not burn in like a lacquer.

---