
Subject: Re: Guinevere layout tip, Cap mounting
Posted by [Forty2wo](#) on Sat, 12 Feb 2005 18:05:31 GMT
[View Forum Message](#) <> [Reply to Message](#)

A good way to mount that big honking 100mf oil cap. Cut a hole in your top plate that the body will pass thru but not the lip, clean well. slide your cap in from the bottom and run a bead of GE silicone RTV around the lip. Smaller caps and parts, just glue to the chassis. I don't mean bathtub calk, this is the stuff they use to glue aquarium's together before filling with hundreds of gallons of water. This stuff is great. It rivals epoxy in its bond yet is flexible enough that parts don't crack off from vibration or flexing. It is resistant to the heat found around tubes. is a very good insulator and if you change your mind you can rescue your part with a sharp knife...John
