
Subject: Re: Rs Filament supply
Posted by [colinhester](#) on Sat, 26 Feb 2005 00:31:04 GMT
[View Forum Message](#) <> [Reply to Message](#)

The way I'm doing it is to wire both Tx's together in parallel to two terminals on a barrier strip. The power comes in after the fuse and switch and neutral is hooked to one terminal and hot is hooked to the other. On my barrier strip, the center terminal makes contact with the chassis and is used as the earth (green wire).....Colin
