
Subject: Re: Rs Filament supply
Posted by [Manualblock](#) on Sat, 26 Feb 2005 00:41:07 GMT
[View Forum Message](#) <> [Reply to Message](#)

Thanks Colin; I wanted to avoid running two AC line cords through the length of the chassis. On mine the Signal circuit is on one side and the power is on the other. But the RS filament trans sits near the 5687 while the AC input is down by the power end. Trying to make the shortest AC path.
