
Subject: Re: Yeap, blown fuse
Posted by [cheetah](#) on Tue, 01 Mar 2005 03:26:45 GMT
[View Forum Message](#) <> [Reply to Message](#)

Why can't you put a 1 ohm resistor between R3 and the plate? Then measuring across this resistor, $15\text{mV}=15\text{mA}$. Impact on circuit should be nil. Joe
