

---

Subject: Re: Yeap, blown fuse

Posted by [PakProtector](#) on Tue, 01 Mar 2005 11:16:33 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

actually, I like Colin's method. Never thought of doing it that way. There is no danger, save for heat generation, as the CCS is dropping all of B+. For short period of time, it shouldn't pose a problem. Just be sure you don't try this from the mu output, as damage could be done to the mosfets, and there is no way to get a real measurement w/o including R3. I am going to try this on my valve pre-where I can't test w/ a 9V out of circuit. Thanks for showing me this method. regards, Douglas

---