
Subject: Re: Mounting Coupling caps
Posted by [Thrint](#) on Wed, 02 Mar 2005 21:14:42 GMT
[View Forum Message](#) <> [Reply to Message](#)

I keep them in the same location and orientation, but glue them to the underside of the chassis with JB Weld. It requires a thicker base x-section...I suspect that your method would work just fine with JB Quick instead of Silicone. That 2-part is tough stuff. Just clean thoroughly first.regards,Douglas
