

---

Subject: Guinevere wired and ready.

Posted by [Manualblock](#) on Tue, 08 Mar 2005 00:29:32 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Well; all the wires are soldered and dressed. I will not power up until tomorrow. I need to check all leads and joints and want to start fresh. I think the only possible problem may lie in those SS things. I mounted the LED's on a separate strip with its own ground. The heater supplies work on both tubes and I am pretty confident of the PS. Time will tell. I am going to use one of the gainclones to test at first just in case! If there are no problems you will hear from me. If you don't hear from me send mass cards to Our Lady Of Lourdes.

---