
Subject: Re: Measuring current

Posted by [PakProtector](#) on Fri, 11 Mar 2005 03:20:21 GMT

[View Forum Message](#) <> [Reply to Message](#)

did it eat into your stock of spares?I would re-word a bit. Don't check between pins one and nine, repeat the measurement procedure for pins one and nine (the anodes).If you attach negative lead to the cathode(pin 3 for pin 1 anode , and pin 6 fo the pin 9 anode) or to of the LED string, you can measure current w/o extinguishing the LED's. Not exactly remomended, as there is less room than the ground terminal offers.Thanks again Colin for teaching me that cool trick.regards,Dogulas
