

---

Subject: Well...

Posted by [PakProtector](#) on Sun, 13 Mar 2005 03:09:40 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

The sensitivity of the hum to the volume control narrows things down significantly. I hate to use the catch all, 'grounding issue' but check to make sure the stuff which should be isolated actually is, and that your signal grounds all meet at the negative side of the volume pot. cathode return, negatives from the RCA jacks( input and output ). then take one connection to the capacitor's ground/negative lug. And then again, there is always the silly unknown. I did something which appeared to be completely unrelated to the line stage circuit and the hum I thought was ac filaments in my amp got remarkably quieter... regards, Dogulas

---