

---

Subject: (300) B - Movie

Posted by [Damir](#) on Mon, 07 Nov 2005 17:48:23 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Huh, what a day... I tried some ideas in a hurry in my super-equipped electronic laboratory. Good news are that modified cascode 5687 driver for 300B works, measured values are very close to calculated/simulated, and the sound is "promising". And then - electric shock through the chest (both hands, of course)...not a big deal, just a little chest and head pain...I've continued with experiments, but then - big HV toroid starts to burn...no big deal, not too expensive. I bought four cheap multiple secondary toroids some time ago, one shorted (primary) after about an hour, and then today I burned another one (primary too)...people who made them don't know what they are doing, for sure. Before you start to complain that maybe hurry and wire-mess, and cheap parts aren't the best way - please remember your faults... (Part 5 - cascode driver coming soon [http://www.aldielyrics.com/lyrics/television/marquee\\_moon.html](http://www.aldielyrics.com/lyrics/television/marquee_moon.html))

---