
Subject: Re: this makes an interesting assumption...
Posted by [Manualblock](#) on Sun, 04 Dec 2005 01:44:23 GMT
[View Forum Message](#) <> [Reply to Message](#)

Does this quote have relevance to this discussion?" As a general rule, the output transformer should have the largest core which is practicle or permissable having regard to cost or other factors. A large core of ordinary silicon steel laminations is usually better than a small core of special low-loss steel."Trying to gather rules to design by.
