
Subject: Re: 300B SE Project, Part 7 - Common cathode 6C45Pi triode driver
Posted by [Damir](#) on Sun, 26 Feb 2006 19:14:22 GMT

[View Forum Message](#) <> [Reply to Message](#)

Yes, some can be even "triggered" sometimes by some sounds/frequencies, I'm pretty sure. But, as I said - without scope we can only guess...If you have similar symptoms, check all your connections/grounding and rewire it - "stopper" resistors close to the pins (non-inductive, say CC), and very short wires.
