

---

Subject: Re: resonance problem

Posted by [RBP](#) on Thu, 29 Mar 2001 03:07:04 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Very possible. you might have one voice coil winding that was rattling.. Just a wire vibrating in the voice coil that should have been laminated down. As per the amp replacement...a screw or nut inside could be buzzing, a ground problem in the amp, or simple amplifier oscillation. Lot's of causes...loose panels Shipping damage internally (Trucking companies do drop things) Things do happen!

---