
Subject: Re: scanspeak 10"

Posted by [Wayne_Parham](#) on Mon, 02 Apr 2001 13:51:08 GMT

[View Forum Message](#) <> [Reply to Message](#)

PiAlign will often pick a smaller box than BoxPlot's "align" function does. Seems like for motors having very large Q, it recommends larger boxes than BoxPlot's align function and with those having smaller Q's, it recommends smaller boxes. It's a different alignment.
