Subject: Re: scanspeak 10" Posted by Wayne_Parham on Mon, 02 Apr 2001 13:51:08 GMT View Forum Message <> Reply to Message

PiAlign will often pick a smaller box than BoxPlot's "align" function does. Seems like for motors having very large Q, it recommends larger boxes than BoxPlot's align function and with those having smaller Q's, it recommends smaller boxes. It's a different alignment.

Page 1 of 1 ---- Generated from AudioRoundTable.com