
Subject: Re: theater 7 x-over

Posted by [Wayne_Parham](#) on Tue, 03 Apr 2001 15:42:18 GMT

[View Forum Message](#) <> [Reply to Message](#)

The plans include the part values. Beyond that, use air core coils, polypropylene caps and non-inductive 10 watt resistors. Connect four resistors in series/parallel to form a higher wattage part of the same resistance value.
