

---

Subject: Re: Sounds great! It may be getting time for me to break out the table saw.  
NT

Posted by [Paul C.](#) on Tue, 15 May 2001 16:59:26 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Dave: I see no reason the woofer would present a problem to a tube amp. For the 1188, you could put a 20 ohm 10 wt resistor in series with the 1188 driver. So, no matter how high the freq, there has to be at least 20 ohms present, right? The, in parallel with the 1188 and resistor, an 8 ohm non inductive resistor. So, now the whole thing looks like 8 ohms. So, come from the hot lead of the spkr's input terminal with a 25 uf cap (10 uf + 15 uf cap paralleled).