

---

Subject: other problem is no one makes 64 ohm  
Posted by [Sam P.](#) on Sun, 10 Feb 2002 20:35:37 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

resistors, I referred to them w/o looking at a chart. 68 is a real value, but four of them gives 17 ohms when you are done! Sam