

---

Subject: Re: Motor impedance

Posted by [Adam](#) on Sun, 10 Mar 2002 21:36:00 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Yep. Your amplifier will be driving the woofer at 16 ohms but driving the compression driver at only 8 ohms. The result will be that you will have to increase the amount of padding on the tweeter by 3 db. Adam