Subject: correction Frame IS metal.. coated with plastic. Doh Posted by dbeardsl on Thu, 28 Mar 2002 03:54:35 GMT View Forum Message <> Reply to Message

They don't have a screen. The vent in the back is about 1 inch. The bump in the back is about 3.5" across and is raised about 3/8". If I stick my finger down in the vent, there is some foam about 2.5" down.ok, I attacked one with a knife, The Frame is Metal, but it is coated in a thin layer of black textured plastic(ABS?). I guess this is to cut down on resonance, cause it sounds like plastic when you tap it.

Page 1 of 1 ---- Generated from AudioRoundTable.com