

---

Subject: Try a proper x-o on the piezos

Posted by [Andy.G](#) on Wed, 03 Jul 2002 10:03:40 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Go to my web site, bottom of right columnrun the 2 piezos in series, not parallel, and reduce the resistor in series with the tweeters in the diagram to about 10 ohms (wag)

Andy G's web site

---