

---

Subject: Re: Amp clipping

Posted by [Wayne Parham](#) on Thu, 11 Jul 2002 15:52:37 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

That's weird. I see from the link you sent that the Jensen speaker has voice coil resistance of around 6 ohms and inductance of around 0.5 millihenry. That is pretty normal for a speaker like this, and similar to that of the Eminence Alpha 8. What's the condition of the voice coil on the Alpha 8? Are they new?

---